

NOTICE TO MARINERS

No 53 (T) of 2019

Port of Southampton – North Thorn Buoy Light Dim

NOTICE IS HEREBY GIVEN that the light on the North Thorn Buoy (50° 47.917'N, 01° 17.836'W) is currently reported as being dim.

Vessels are requested to proceed with caution when navigation in this area. Ahead of their passage, mariners may also request shipping information from Southampton VTS on VHF Channel 12.

This notice will be self-cancelling upon rectification of the defect.

**Vessel Traffic Services Centre
Ocean Gate, Atlantic Way
Southampton**

**Captain P J A Buckley
Harbour Master**

20th November 2019

**Owners, Agents, Charterers, Marinas, Yacht Clubs and Recreational Sailing
Organisations should ensure that the contents of this Notice are made known to the
masters or persons in charge of their vessels or craft.**