

## **NOTICE TO MARINERS**

**No 3 (T) of 2018**

### **Port of Southampton – Central Solent – Black Jack**

### **Navigation Buoy - Out of Position**

**NOTICE IS HEREBY GIVEN** that the Black Jack navigation buoy in the Thorn Channel is currently out of position by approximately 30m on a south-east bearing of 145°. The current position of the buoy is **50° 49.116'N, 01° 18.073'W**.

Vessels are requested to proceed with caution when navigation in the vicinity of the Black Jack buoy. Ahead of their passage, mariners may also request shipping information from Southampton VTS on VHF Channel 12.

This notice will be self-cancelling upon relocation of the Black Jack buoy to its charted position.

**Ocean Gate  
Atlantic Way  
Southampton, SO14 3QN**

**Captain P J A Buckley  
Harbour Master**

27<sup>th</sup> February 2018

**Owners, Agents, Charterers, Marinas, Yacht Clubs and Recreational Sailing Organisations should ensure that the contents of this Notice are made known to the masters or persons in charge of their vessels or craft.**