


**NOTICE TO MARINERS**

**No 41 (T) of 2018**

**Port of Southampton – Southampton Water –  
Hamble Cliff Mooring Buoy – Missing from Station**

**NOTICE IS HEREBY GIVEN** that the Hamble Cliff Mooring Buoy is currently missing from its charted position (50° 51.290'N, 01° 20.554'W) and has been recovered ashore.



Vessels are requested to proceed with caution when navigation in this area. Ahead of their passage, mariners may also request shipping information from Southampton VTS on VHF Channel 12.

**Vessel Traffic Services Centre  
Ocean Gate, Atlantic Way  
Southampton**

**Captain P J A Buckley  
Harbour Master**

19<sup>th</sup> September 2018

**Owners, Agents, Charterers, Marinas, Yacht Clubs and Recreational Sailing  
Organisations should ensure that the contents of this Notice are made known to the  
masters or persons in charge of their vessels or craft.**