

## Local Notice to Mariners


Number 30(T) of 2025

23/01/2025

### Lains Lake Buoy Off Station

**NOTICE IS HEREBY GIVEN** that Lains Lake port hand lateral buoy is missing from its charted position 50° 51' 32.66N, 001° 21' 34.20W. Arrangements are currently being made to redeploy the buoy. An update will be provided when the buoy is re-laid.

Mariners are advised to navigate with caution. Additional information can be requested from "Southampton VTS" on Channel 12.



This notice will be self-canceling when Lains Lake buoy is reinstated.

**Steven Masters,**  
Harbour Master