

## NOTICE TO MARINERS No 19(T) of 2018

## Port of Southampton – Southampton Water – Calshot Light Float Fog Signal Inoperative

**NOTICE IS HEREBY GIVEN** Calshot Light Float (position 50° 48.35'N, 01° 17.64'W) Fog Signal is Inoperative.

Our Engineers are working to rectify the Fog Signal as soon as possible but it is expected to take approximately 1 week

This Notice will be self-cancelling on rectification of this fault.

Ocean Gate
Atlantic Way
Southampton SO14 3QN

Captain P J A Buckley Harbour Master

23<sup>th</sup> May 2018

Owners, Agents, Charterers, Marinas, Yacht Clubs and Recreational Sailing Organisations should ensure that the contents of this Notice are made known to the masters or persons in charge of their vessels or craft.