


NOTICE TO MARINERS

No 48 (T) of 2018

Port of Southampton – 40 Berth, Eastern Docks – Damage to Quay Face

Notice is hereby given that the quay face on 40 berth, Eastern Docks, between **bollards 24A and 26** has deteriorated to a condition where it is unsafe for use. The condition of the quay wall is such that there is an immediate danger of falling masonry.

The Harbour Master has declared an exclusion zone between bollard 24A and 26. The affected area will be marked by signage and all vessels should navigate with extreme caution. Access to the quay edge in the affected area is also prohibited.



Signage to be used:



**Vessel Traffic Services Centre
Ocean Gate
Atlantic Way
Southampton**

**Captain P J A Buckley
Harbour Master**

11th October 2018

Owners, Agents, Charterers, Marinas, Yacht Clubs and Recreational Sailing Organisations should ensure that the contents of this Notice are made known to the masters or persons in charge of their vessels or craft.