

## **NOTICE TO MARINERS**

**No 11(T) of 2019**

### **Port of Southampton – Southampton Water – Deans**

### **Lake Buoy – Light Extinguished**

**NOTICE IS HEREBY GIVEN** that the light on the Deans Lake navigation buoy in Southampton Water (50° 51.402'N, 01° 21.584'W) is currently extinguished.

Vessels are requested to proceed with caution when navigation in the vicinity of the buoy. Ahead of their passage, mariners may also request shipping information from Southampton VTS on VHF Channel 12.

This notice will be self-cancelling upon rectification of the defect.

**Vessel Traffic Services Centre  
Ocean Gate, Atlantic Way  
Southampton**

**Captain P J A Buckley  
Harbour Master**

8<sup>th</sup> February 2019

**Owners, Agents, Charterers, Marinas, Yacht Clubs and Recreational Sailing Organisations should ensure that the contents of this Notice are made known to the masters or persons in charge of their vessels or craft.**