

NOTICE TO MARINERS

No 29(T) of 2017

Port of Southampton – Bourne Gap Navigation Buoy – Light Extinguished

NOTICE IS HEREBY GIVEN that the Bourne Gap Navigation Buoy Light (Fl (1) R 3s) in the Thorn Channel (50° 47.829'N, 01° 18.343'W) is currently reported as Extinguished. Mariners are advised to proceed with caution when operating in this vicinity.

This notice will be self-cancelling upon rectification of the defect.

**Vessel Traffic Services Centre
Ocean Gate, Atlantic Way
Southampton**

**Captain M Phipps
Harbour Master**

17th August 2017

Owners, Agents, Charterers, Marinas, Yacht Clubs and Recreational Sailing Organisations should ensure that the contents of this Notice are made known to the masters or persons in charge of their vessels or craft.